

25X1

SECRET


25X1A

CENTRAL INTELLIGENCE AGENCY

ATTACHMENT

- 1 -

SECTION OF STALIN WORKS AT MOST (IRUK N 51/F 13)



25X1

CONFIDENTIAL

CENTRAL INTELLIGENCE AGENCY

ATTACHMENT

- 2 -

25X1A

Key to the sketch of Stalin Works at Most

1. Enterprise hospital.
2. Unmarried employees' quarters.
3. Gate-room.
4. Watchtower.
5. Plant kitchen and mess hall.
6. Benes House (former hotel, now being rebuilt as a hospital).
7. Concrete water tank, 20 m x 10 m.
8. Pump.
9. Cooling tower.
10. Laboratory and machine shop.
11. Destroyed cooling tower.
- 12., 13. Destroyed buildings.
14. Locksmith's workshop, autogenous and electric welding shop.
15. Personnel department.
16. Bus stop.
17. Bus garages.
18. Bus dispatcher's office.
19. Office of the plant guard.
20. Social department.
21. Plant dispensary.
22. Accounting office.
23. Ball bearings warehouse.
24. Entrance.
25. Welding shop, room for boiling solvents.
26. Store of material for workshops and solvents.
27. Purchasing and sales department and foreign trade.
28. Air-raid shelter.
29. Two entrances for trucks (not shown on sketch).
30. Air-raid shelter, used as warehouse for maintenance department.
31. StB office.
32. SNB post.
33. Newly erected reinforced concrete building, 60 m x 20 m. It is to serve for testing fuels for jet planes.
34. Teletypewriter, telephone switchboard.
35. Main laboratory.
36. Newly erected laboratories.
37. Construction department.
38. Pay office.
39. Experimental laboratory.
40. Entrance.
41. Iron stock warehouse.
42. Auto workshops.
43. Vulcanization workshop.
44. Garages.
45. Underground fuel tank.
46. Fire brigade station.
47. Repair workshop for measuring instruments.
48. Control section.
49. Transportation department.
50. Planning department.
51. KSC secretariat.
52. Warehouse of operational control section.
53. Bulletin board.
54. Tank car loading platform.
55. Air-raid shelter (serves as store of measuring instruments).
56. Workshop for maintenance of steam heating plant.
57. Production of pentane and butane.
58. Locksmith workshop.
59. Valve department.
60. Paint and varnish warehouse.
61. Maintenance department.
62. Smithy.
63. Auto repair shop.
64. Machine shops

CONFIDENTIAL

25X1

25X1

SECRET, [REDACTED]

CENTRAL INTELLIGENCE AGENCY [REDACTED]

ATTACHMENT

- 3 -

25X1A

65. Oxygen storage.
66. Air-raid shelter.
67. Locksmith's workshop.
68. Oxygen tanks.
69. Oxygen department.
70. Main repair workshops.
71. Electric welding, smithy and foundry.
72. Manufacture of liquid oxygen.
73. Pentane station, gasoline station.
74. Oxygen and acetylene tank storage.
75. Air-raid shelter (store of tools).
76. Workers' council and enterprise management.
77. Air-raid shelter.
78. Gas filtration plant.
79. Machine shops.
80. Underground concrete gasoline tank with three towers.
81. Control station for gasoline tanks, specially guarded.
82. Buildings for production of byproducts (phenol, tar etc.)
83. Generators.
84. Gas compressors.
85. Unknown
86. Machine shop for production of hydrogen.
87. Hydrogen station.
88. Hydrogen tank filling station.
89. Gas compressors.
- 90., 91. Unknown.
92. Coke cooling station.
93. Repair shop for electric motors and compressors.
94. Coke pressing station.
95. Carbonization furnaces.
96. Cooling towers.
97. Newly built laboratory.
98. Steam power plant.
99. Chimneys about 45 m high.
100. Air-raid shelter.
101. Warehouse.
102. Water cooling towers.
103. Carbonization. Furnaces.
104. Distillation station.
105. Gasoline station.
106. Maintenance workshop for carbonization department.
107. Store of coal.
108. Gas pumping station. shop.
109. Machine shop.
110. Experimental laboratory.
111. Mess hall.
112. Maintenance locksmith's shop.
113. Gateroom near the mine "Minerva".
114. Buildings of the railway department.
115. Gas tanks.
116. Machine shop and experimental laboratory.
- 117, 118, 119 Gasoline pumping stations.
- 120, 123. Materials warehouse.
124. Gate.

SECRET, [REDACTED]

25X1